

July 18, 2003

Ernest Crowley
PO Box 188
Minden, NV 89423

Mr. Curtis Millsap
1677 Hot Springs Road
Carson City, NV 89706

Dear Curtis,


I wish to inform you of a maintenance repair we had to complete at Pineview Estates in Gardnerville.

On Thursday, June 12, 2003, I was informed of some standing water between Highway 395 and the foot of the slope on the west side of Unit II. Friday, I investigated and found a slow leak in Leachfield #1 at this location. This is the oldest field in the subdivision (4 or 5 years old).

I made an appointment with Steve Brown Construction to meet me on site Monday morning and to have equipment available. On Monday morning, I met Steve Brown at the site and we determined it was a failure of this field. We moved in equipment to build 4 new leachfield runs. On Tuesday morning Lumos Associates Engineer Tom Young designed a new field to supplement the existing field and construction was started at 7:00am. By Wednesday the situation was controlled and repairs were completed Thursday. A new distribution system will be in place next week that should improve the field.

No more leaks exist and the area is cleaned up. We moved as fast as the work could be done.

Sincerely,



Ernest Crowley
Project Manager
PTP Corporation

cc: Katherine Rao
Environmental Protection Agency
Ground Water Office (WTR-9)
75 Hawthorne Street
San Francisco, CA 94105